



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA129



Photo 1 – View of balloon at examination (Photo Courtesy of FAA)



Photo 2 – View of vertical load tape damage (Photo Courtesy of FAA)



Photo 3 – View of vertical load tape damage (Photo Courtesy of FAA)



Photo 4 – View of load tape flame and heat damage (Photo Courtesy of FAA)