



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA231



Photo 1 – View of helicopter from right side (Photo Courtesy of FAA)



Photo 2 – View of helicopter from left side (Photo Courtesy of FAA)



Photo 3 – View of helicopter from front (Photo Courtesy of FAA)



Photo 4 – View of area of missing engine cowl (Photo Courtesy of FAA)



Photo 5 – View of broken cowl attachment bracket (Photo Courtesy of FAA)



Photo 6 – Close-up view of horizontal stabilizer damage (Phot Courtesy of FAA)



Photo 7 – View of right horizontal stabilizer (Phot Courtesy of FAA)



Photo 8 – View of detached engine cowl (Photo Courtesy of FAA)