

Date	Total Time In Service	Total Time Since Overhaul	Tach or Recording Meter Time

Balance Forward

N8149R

Description of Work Performed
Certificate Number & Signature of Technician Performing Work

TACH TIME - 3657.3

Page: 29

01/16/2023

PILOT REPORTS SMOKE IN COCKPIT DURING FLIGHT ON 01/07/2023. AFTER TROUBLESHOOTING, FLOWN AND TESTED, AIRCRAFT RETURN TO SERVICE WITH NO SMOKE.
Inspection was determined to be in an airworthy condition.

ROBERT GAINOR [REDACTED]

N8149R

Tach 3701.8

2/27/2023

Routine 50 hr inspection accomplished I/A/W Piper Warrior checklist. Oil and filter changed. Serviced oil sump with 8quarts of Phillips x/c 20w/50 and installed AA48110-2 oil filter. Ground run-up satisfactory, no leaks or defect noted. Return aircraft to service.
Robert Gainer A&P [REDACTED]

Totals - Carry Forward

