

ERA24LA279

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of wreckage (Courtesy of FAA)



Photograph 2 - Postaccident view of wreckage (Courtesy of FAA)



Photograph 3 & 4 - Two views of partially occluded fuel line from fuel pump inlet manifold



Photograph 4 - Cracked fuel hose from fuel pump inlet manifold



Photograph 5 - Fuel pump outlet manifold hose and fitting installation



Photograph 6 - Partially occluded fuel hose from fuel pump outlet manifold