	ENGINE LOG	Serial No.
	Holly Springs Marshall Co. Airport	nbe
AIRCRAFT, INC.		Page 1
checked. Crankcase dye checked Off 6 #LW15278 bearing; 1 #AN565B16 ring; 8 #71907 plate; 2 #76788 pin; 1081 snap ring; 1 #06B23072 o-rin #18M19389 rod bearing; 12 #SL74 button; 2 #LW13641 mag rubber; 6 #RA-MS9144-01 prop governor gash MAKE LYCOMING SERIAL NO.	WAS REPAIRED AND INSPECTED IN ACC	s new parts: 2 #18A19441 bearing; #STD1211 plug; 8 #LW14820 snap 8 #71903A bushing; 1 #MS16625- d bolt; 12 #LW12186 rod nut; 12 FD1821 hose; 8 #LW12892 rocker ket set; 1 #72198 piston pin plug; 1 gent Oil. Engine Run On Test Cell. TOTAL TIME UNKN CORDANCE WITH CURRENT FEDERAL
AMATION DECLII ATIONS AND WAS I	FOUND AIRWORTHY FOR RETURN TO SE AGENCY UNDER WORK ORDER NO. FOR REPAIR STATION NO. JUJR30	J4184 DATE: 06-26-2003

1							M	
	N4166C	N4166C	GBOOK ENTRY Tach: 3115.9	SMOH: 1143.1	G Serial No			
7	completed 100 hour inspe 7/80, #3-73/80, #4-73/80, comshell 100W Plus and 0	CH48103-1 filter. Washed	art 43. Compressions as inged oil and filter. Servic i, ran up and leak checke tified above was repaired	d. This aircraft.	MARKS	at ma	Signature	License Number
arrane arcraft engine, properties of approach and is approved for return to service. current Regulations of the Federal Aviation Administration and is approved for return to service. Perfect details of the repair are on file at this repair station under Work Order 23500. I certify that Perfect details of the repair are on file at this repair station under Work Order 23500. I certify that Perfect details of the repair are on file at this repair station under Work Order 23500. I certify that Perfect details of the repair are on file at this repair station under Work Order 23500. I certify that					_E -150	10 50	enter the same	\$ 16 Sep
ě	saned Soned	thorized representative		Rite-Way Aviation, Inc.	10.29.31	124数 20	22.05 -	0302
		ENGINE L	OGBOOK ENTRY			and and	and John	4 1.4
	08/18/2021	N4166C	Tach: 3130.2	SMOH: 1157.4				
	Pus and CH48103-1 filte propeller or appliance ide Aviation Administration a this repair station under to with a(n) 100 hr. inspect.	er. Washed, ran up and it entified above was repaire and is approved for return	eak checked. This aircra ed and inspected with cur to service. Pertinent det- ify that this engine has be be in an airworthy condi-	as follows: #1-72/80, #2-74/ with 8 quarts Aeroshell W100 fft, airframe, aircraft engine, rrent Regulations of the Federalls of the repair are on file a een inspected in accordance ition. Rite-Way Aviation	eral t	ta Must Bear Mechanic, and Imber MUST	the Endorsement of his Rating and be Shown.	