From:
To:
Subject: N611E accident

Date: Tuesday, February 16, 2021 11:15:07 AM

Attachments:

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Good morning Brian,

Attached is another video, using the wrench that he made to tighten the fitting, then using a torque wrench and torqueing the fitting to the minimum 150 in. pounds (range is 150 to 195). As you can see, using the torque wrench, the line will not loosen by hand.

Mark V. Keefer Principal Maintenance Inspector Tampa FSDO/AFG-800-SO35

Office: