				TIME	DATE	
RECORD OF VISIT	CONFERENCE	OR TELEPHON	E CALL	8:30 - 1:00	8/5/2020	1
NAME (S) OF PERSON (S) CONTACTED	OR IN CONFERENCE AND LOCATION	DN N			R OUT	TING
					SYMBOL	INITIALS
Location: Fernandina	Beach Aircraft Main	tenance, 3990 Cer	nturion Wa	y Fernandina		
Beach 32034						
FAA: Robert Melcher	(ASI)	Airman: Sherman K	eller A&P/	IA		
N31720 Inspection and landing gear swings related to accident on 7/25/2020.						
DIGEST					1	
Arrived at Fernandina	Beach Aircraft Maint	tenance facility and	l inspected	l and photogra	ph aircraf	t
damage. Damage was				•		
830.2.The left wing sk		•			g up into th	ne upper
wing skin after the lan	ding gear folded as p	part of the accident	sequence			
The engine was un-co	wled and inspected	for any obvious sig	ns of prob	lems and the	fuel was	
inspected for any sign	•	•				
The right MLC was inc	anastad for gararal a	andition and coouri	tv. A landii	na anar oyton	sion and r	otraction
The right MLG was instest was performed by	. •		•			BUACUOII
		, , , , , , , , , , , , , , , , , , ,		9		
*Left gear actuator dis		0 . 0	and locke	d		
* Right gear door disc		•				
Nose gear doors discExtension and retract		=	ms only.			
	,	-	,			
Performed normal and						lications
were normal. The righ	t MLG and NLG retra	acted and extended	d normally,	no anomalies	noted.	
conclusion, action taken, or requ Conclusion: The right		extended in both t	he normal	and emergen	CV	
modes.					- ,	
Action Taken: Report	ed findinas to NTSB	IIC. Reported findi	nas to FLN	/I and docume	nted in PT	 ГRS.
			<u> </u>			
DATE	TITLE	1	SIGNATURE			
8/5/2020	Aviation Safety Insp	ector	ROBERT E MELCHER			

DIGEST (CONT)		