

N951X

Accident at ANE

Anoka, MN

N951X

12 O'clock view



N951X

6 O'clock view



N951X

9 O'clock view



N951X

Horizontal Stabilizer



N951X

Wing view



N951X

Nose steering and rudder inoperative due to the nose gear tube is bent inside of its slide which caused the steering bellcrank to jam against the firewall preventing the rudder or nose steering from turning.

