

Lindberg Joshua

From: Folkerts Michael
Sent: Wednesday, January 5, 2022 8:13 AM
To: CEN_Notifications; Gallo Mitchell; [REDACTED]
Subject: 1/1/2022 - PORT ARANSAS, TX (RAS) - N8816T - C182 - power loss on approach - 1 POB - minor injuries - left wing damaged
Attachments: Scan01-01-2022-201228.pdf; image_6487327e.jpg; IMG-6649.jpg; image_6487327d.JPG

Thanks Mike

Hi Mitch

This is loaded up in SAFTI for assignment

1 POB, minor injuries.

Power loss on final approach after a parachutist was dropped from about 9,000 ft msl.

The pilot told me he didn't use carb heat at all during the descent "because the engine was hot from the climb".....

[REDACTED]

[REDACTED]

Mike

Mr. Folkerts,

Met the owner at the aircraft yesterday. Limited inspection of the fuel system revealed no external issues and fuel was present in both wing tanks. Structural damage on the left wing leading edge outboard as the photos show. Prop was turning when he hit the ground, found scrapes and scratches on the blades. Please send me the NTSB case number so I can start the -23 today.

Respectfully,

Michael D. Gabster "Mike"
Aviation Safety Inspector
Federal Aviation Administration
Flight Standards Office, SW-17
10100 Reunion Place, Suite 200
San Antonio, Texas 78216-4118

[REDACTED]

From: [REDACTED]
Sent: Saturday, January 1, 2022 6:19 PM
To: [REDACTED]
Subject: GENERAL AVIATION ACCIDENT/INCIDENT @ PORT ARANSAS, TX (RAS)

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

GENERAL AVIATION ACCIDENT/INCIDENT | N8816T | PORT ARANSAS, TX (RAS) 01-01-2022 1820Z

Event ID: 697216
Zulu Date/Time: 01/01/2022 1820Z
Local Date/Time: 01/01/2022 1220 CST
Event Type: GENERAL AVIATION ACCIDENT/INCIDENT
Region: ASW
Location: PORT ARANSAS, TX (RAS)
Reporting Facility: LEIDOS AFSS
N-Number: N8816T
Aircraft Type: C182
Departure Airport: RAS
Arrival Airport: RAS
POB: 1
Injuries: NONE
Damage: EXTENT UNKNOWN
Message Text: PORT ARANSAS, TX (RAS): N8816T, C182, RAS-RAS, ACFT FINISHED CONDUCTING PARACHUTE OPERATIONS AND PILOT WAS POWER TO IDLE ON APPROACH TO RWY 12. PILOT WAS LOW AND GOT NO THROTTLE RESPONSE. ACFT LANDED SHORT OF RWY IN MARSH DAMAGING WING AND GEAR. POB: 1, INJURIES: NONE, DAMAGE: EXTENT UNKNOWN. ATC SERVICES: CRP APCH. 01/01/2022 1820Z
Groups Notified: CSA NTSB; SAT FSDO
Created By: STEVE.BONO
URL: [REDACTED]

Federal Aviation Administration | 800 Independence Avenue SW | Washington DC, 20591
Information contained herein is based on preliminary reports and is subject to revision
Public availability to be determined under 5 USC 552

Please do not reply to this email; it is sent from an unmonitored address. For questions about this event or how to receive events like this one, you may contact the Regional Operations Center at [REDACTED]