2020-05-20, 0937L, N612R FLIPPED OVER ON TAKEOFF AFTER LAUNCHING FROM SURFSIDE SEA BASE, LINO LAKES, MN WX VFR, WINDS 120/09 PERHAPS UP TO 13KTS













FIREWALL AND ENGINE AND ENGINE MOUNTING FRAME APPEARS TO HAVE NO VISIBLE DAMAGE.




NO APPARENT FIREWALL OR ENGINE OUNT DAMAGE.











SUSPECT; WITH A SLIGHT QUARTERING TAILWIND FROM THE LEFT, WHILE MAKING A LEFT TURN THERE ARE CENTRIFIGUL FORCES ACTING TO THE OUTSIDE OF THE TURN (TO THE RIGHT), AND AT SOME POINT THE LEFT QUARTERING TAILWIND DOES BECOME A DIRECT LEFT CROSSWIND AMPLIFYING THE EFFECT OF A FORCE TO LIFT THE LEFT WING.

POTENTIALLY A GUST MAY HAVE BEEN PRESENT AS WELL.

PILOT AT CONTROLS REPORTS; A FORWARD RIGHT DIRECTION OF TRAVEL AS THE FRONT OF THE RIGHT FLOAT SINKS DOWN IN THE WATER.