

Figure 1. Exemplar gasket (HMD22LR001-HAZ-005 taken from TILX731779 (line 37))



Figure 2. Damaged gasket (HMD22LR001-HAZ-004 taken from TILX731758 (line 65))




Figure 3. Damaged portion of gasket (HMD22LR001-HAZ-006 taken from TILX731458 (line 71))



Figure 4. Closeup photograph of surface of exemplar gasket (HMD22LR001-HAZ-005 taken from TILX731779 (line 37))




Figure 5. Micrograph of surface split in exemplar gasket (HMD22LR001-HAZ-005 taken from TILX731779 (line 37))