

BNSF Railway

BNSF Inspection Report - Insulation Tests & Inspections

Inspection #: 001003430421 ~ Form Type: INSULATION ~ 10 Year

Division: PR	Asset ID: BABYEYR
Subdivision: PIKES PEAK	Test Date: 2019-09-23
Line Segment / Milepost: 0477 ~ 109.66 - 109.66	State: CO
Location / Highway Name: SOUTH_BRAGDON	
County: PUEBLO	
Employee's Name: PII [REDACTED]	Gang ID: PII [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance

Operations With Measurements

<u>INSULATION (FRA-236.108)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
RESISTANCE	T-5-10-EA JCT BOX-EA SIGNAL	09/23/19	Tested OK			B028145
RESISTANCE	T-5-10-EB JCT BOX-EB SIGNAL	09/23/19	Tested OK			B028145
RESISTANCE	T-5-10-SW JCT BOX-SWITCH	09/23/19	Tested OK			B028145
RESISTANCE	T-5-10-SWITCH JCT-SWITCH	09/23/19	Tested OK			B028145
RESISTANCE	T-5-10-WA JCT BOX-WA SIGNAL	09/23/19	Tested OK			B028145
RESISTANCE	T-5-10-WB JCT BOX-WB SIGNAL	09/23/19	Tested OK			B028145
RESISTANCE	U-12-14-HOUSE-SWITCH	09/23/19	Tested OK			B028145
RESISTANCE	U-3-6-HOUSE-SWITCH	09/23/19	Tested OK			B028145
RESISTANCE	U-5-6-HOUSE-SIG. EA	09/23/19	Tested OK			B028145
RESISTANCE	U-5-6-HOUSE-SIG. EB	09/23/19	Tested OK			B028145
RESISTANCE	U-5-6-HOUSE-SIG. WA	09/23/19	Tested OK			B028145
RESISTANCE	U-5-6-HOUSE-SIG.WB	09/23/19	Tested OK			B028145