

Photo 1 – Left main gear temporarily attached



Photo 2 – Left wing tip bent up, Spar bent