



Photo 1 – front view, left wing spar bent (Owner)



Photo 2 – Left wing tip, bent spar (Owner)



Photo 3 – left wing view from bottom. (Owner)