



Photo 1 – Digital Photograph Provided by Flying Club. Left Forward Quartering View of the Airplane Taken Before the Accident.



Photo 2 - Digital Photograph Provided by Flying Club. Pilot's Side of the Instrument Panel Before 4/1/2019 Flight.



Photo 3 – NTSB Digital Photograph. View Depicting Wreckage on the Ground and Among Trees.



Photo 4 - NTSB Digital Photograph. View Depicting Right Wing Section Suspended in Tree.



Photo 5 - NTSB Digital Photograph. View Depicting the Resting Position of the Main Wreckage Including the Cockpit Section, Engine Assembly.



Photo 6 - NTSB Digital Photograph. Close-Up View of the Engine Assembly at the Resting Position. Note the Extensive Fire Damage.



Photo 7 - NTSB Digital Photograph. View Looking Forward From Behind Left Wing During Follow-Up Examination.



Photo 8 - NTSB Digital Photograph. View Taken Forward of Right Wing During Follow-Up Examination.



Photo 9 - NTSB Digital Photograph. View of the Aft Empennage Taken During Follow-Up Examination. Note the Extensive Fire Damage to the Fuselage Forward of the Attached Left Horizontal Stabilizer.



Photo 10 - NTSB Digital Photograph. View of the Separated Right Horizontal Stabilizer and Elevator Taken During Follow-Up Examination.



Photo 11 - NTSB Digital Photograph. Frontal View of the Engine Assembly with Attached Propeller During Follow-Up Examination. Note the Propeller Blade Bending.



Photo 12 - NTSB Digital Photograph. View of the Propeller Following Separation From the Engine During Follow-Up Examination. Note the “S” Type Blade Bending of Both Blades.