



**Photo 1 – FAA Digital Photograph. View of a fractured Engine Mount Tube.**



**Photo 2 - FAA Digital Photograph. View Depicting the Wrinkles in the Upper Skin of the Left Wing.**



**Photo 3 - FAA Digital Photograph. View Depicting the Wrinkles in the Lower Skin of the Left Wing.**