



**Photo 1 – Digital Photograph Provided by FAA. View Depicting the Ground Scar on the Runway Made by the Nose Landing Gear and the Inverted Airplane.**





**Photo 2 - Digital Photograph Provided by FAA. View Depicting the Substantial Damage to the Rudder Flight Control Surface.**





**Photo 3 - Digital Photograph Provided by FAA. Left Side View of the Inverted Airplane At the Accident Site, and the Nose and Right Main Landing Gears visible. Note the Aft Displaced Nose Landing Gear.**



**Photo 4 - Digital Photograph Provided by Owner/Pilot. Right Side View of the Nose Landing Gear Following Recovery of the Airplane. Note the Aft Displacement of the Nose Gear Leg.**