


ERA23LA121

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident site (Photo Courtesy of FAA)



Photograph 2 - Annotated view of the accident site (Photo Courtesy of FAA)



Photograph 3 - View of the engine and propeller (Photo Courtesy of FAA)



Photograph 4 - View of the thermally damaged fuselage and wings (Photo Courtesy of FAA)




Photograph 5 - View of the thermally damaged cockpit panel (Photo Courtesy of FAA)



Photograph 6 - View of the throttle quadrant (Photo Courtesy of FAA)



Photograph 7 - Additional view of the throttle quadrant (Photo Courtesy of FAA)



Photograph 8 - Additional view of accident site with FAA annotations (Photo Courtesy of FAA)

Intentionally Left Blank