



Photo 1 – Screenshot Capture from Airport Security Approach 13 Camera Depicting the Airplane immediately Before Ground Contact.



Photo 2 – NTSB Digital Photograph. Frontal View of the Airplane at the Accident Site. Note the Deformation to the Leading Edges of Both Wings.



Photo 3 - NTSB Digital Photograph. Left Side View of the Airplane at the Accident Site. Note the destroyed Cockpit Area.



Photo 4 - NTSB Digital Photograph. Rear View of the Airplane at the Accident Site.



Photo 5 - NTSB Digital Photograph. Right Side View of the Airplane at the Accident Site.



Photo 6 - NTSB Digital Photograph. View of the Separated Propeller at the Accident Site. Note the Blade Bending.



Photo 7 - NTSB Digital Photograph. Frontal View of the Engine at the Accident Site. Note the Fractured Crankshaft.