



Photo 1 – Photograph Provided by Tiffany Melton. Left Forward View of the Accident Helicopter Taken July 3, 2019 at 1355 EDT.



Photo 2 - Photograph Provided by Bahamian Accredited Representative. View of the Inverted Main Wreckage Under Water Before Recovery.



Photo 3 - Photograph Provided by Bahamian Accredited Representative. View Depicting the Fuselage During Recovery.



Photo 4 - Photograph Provided by Bahamian Accredited Representative. Left Side View of the Fuselage During Recovery.



Photo 5 – NTSB Digital Photograph. Left Side View of the Fuselage Following Recovery.



Photo 6 - NTSB Digital Photograph. Right Side View of the Fuselage Following Recovery.



Photo 7 - NTSB Digital Photograph. Right Side View of the Fuselage Following Recovery.



Photo 8 - NTSB Digital Photograph. Right Side View of the Aft Row Seats Remaining Installed Following Recovery.



Photo 9 - NTSB Digital Photograph. Left Side View of the Middle Seat and Forward Row Seats Installed Following Recovery.



Photo 10 - Photograph Provided by Bahamian Accredited Representative. View of the Recovered Tail Rotor Assembly. Note the Fractured Tail Rotor Blades.