



**Photo 1 – Digital Photograph From FAA. Left Forward Quartering View of the Airplane at the Accident Site.**



**Photo 2 – Screen Shot from Video Taken After the Accident. View of the Upper Wing Skin of the Left Wing With a Hole Above the Location of the Trunnion in a Normally Installed Position.**



**Photo 3 - Digital Photograph From Airport Manager. View Depicting the Displaced Left Main Landing Gear. Note the Hole Punctured in the Upwards Direction of the Upper Wing Skin.**



**Photo 4 - Digital Photograph From Airport Manager. View Depicting the Fractured Left Trunnion and the Forward Trunnion Fitting.**



**Photo 5 – FAA Digital Photograph. Forward View of the Airplane During Recovery. Note the Compression Wrinkle on the Upper Wing Skin of the Right Wing Just Outboard of the Fuel Cap.**