



Photo 1 – View of left wing showing buckling damage on upper outboard section



Photo 2 – Close-up view of left damaged wing



Photo 3 – Disassembled left brake master cylinder w/ damaged O-ring circled in red



Photo 4 – Damaged O-ring showing pinch and cut