

From: [Folkerts Michael](#)
To: [Liedler Courtney](#)
Cc: [Aguilera Jason](#)
Subject: Little Falls, MN - N7013W accident -- duty officer information
Date: Wednesday, May 13, 2020 12:13:26 PM
Attachments: [N7013W.pdf](#)

Hi Courtney,

The pilot of N7013W provided the following information during a phone conversation:

- The pilot recalled the accident occurring about 1300 CDT. He was planning fly locally at the Little Falls, MN airport (LXL)
- On initial takeoff, after climbing to about 100 ft agl, the aircraft entered a left turn that he wasn't able to counteract.
- The aircraft subsequently impacted the ground to the left side of the runway.
- The pilot did not think there were any issues related to a loss of engine power or the weather.
- The flight was his first since July 2019, when he had started to rebuild the aircraft. He did not have pilot's license; he'd flown about 20 hours in a Cessna 152 as a student.
- The pilot stated he did not possess an aircraft mechanic's license; he had often worked as a mechanic on cars.
- He described his injuries as minor, with no bone fractures or hospitalization.

Attached is FSDO provided information.

Blue Skies ..

Mike