



Laura Abraham  
Air Safety Investigator  
Central Region

**Date:** April 16, 2024

**Subject:** CEN24FA360

**Contact:** Mr. Luke Stanford, son of pilot, telephone conversation

Mr. Stanford stated that he spoke with his father, and his father told him that the engine started to sputter while operating on the right main fuel cell. He said his father switched to other fuel cells, but that did not help with the engine issue. Mr. Stanford said his father switched back to the right main fuel cell when switching to other fuel cells did not work.

---end summary---