



Kristyn Blocher
Air Safety Investigator
Western Pacific Region

Date: 08/02/2023

Subject: WPR23LA273

Contact: Tom Powers, Pilot/Owner, [REDACTED]

When asked by telephone to clarify his answer to the question, "Were there any preaccident mechanical malfunctions or failures of the airplane, precluding normal operation?", Mr. Powers responded by email:

"For clarification there was no pre failure of anything prior to landing."