

MOTOR CARRIER ATTACHMENT

New York State Department of Transportation

Driver/Vehicle Examination Report

Louisville, NY

HWY23FH005

(7 pages)

		DRIVER/	VEHICLE EX	(AMINATIO	N REF	ORT		Query Cent	tral 3.4
New York State Dep Commercial Motor 50 Wolf Road, POD Albany, NY 12232 Phone:	Vehicle Insp	•	ı		In St In	spectio art: 11: spectio	umber: N on Date: 01 06 AM ET on Level: ection Typ	End: 02:56 I - Full	
LBFNY LLC PO BOX 123 CATO, NY 13033-01 USDOT#: 03773075 MC/MX#: 0000000 State#:	Pho	one#: ax#:		Licens Date o CoDriv Licens	se#: V-1 of Birth: ver:		RES, CHF		tate: OT tate:
Location: RAY BRO Highway: SH86 County: ESSEX, NY		RESIDENCY	-	ISVILLE, NY : LISBON, NY	Shippe	Bill c	of Lading: o: PASSE	NGER	
VEHICLE IDENTIFIC Unit Type Make Yea 1 BU CHEV 2013	r State Plat	<u>te # Ec</u> 8787B	<u>uipment ID</u> 1G	<u>VIN</u> B6G5BG2D115		<u>3VWR</u> 4,200	CVSA #	New CVSA #	<u>OOS#</u> YES
Left N/A	ENTS 2 N/A N/A IYDR								
VIOLATIONS									
<u>Vio Code</u> 396.3A1	<u>Section</u> 396.3(a)(1)	Unit 1	<u>OOS</u> <u>Citation #</u> N	<u>Verify</u> <u>Cras</u> N N	lı a b	nspection ccessori roken of	es: Exhaust	ed d maintenance of hanger rusted a ot supported as	ind
393.62C	393.62(c)	1	Y	UY	v	vindows	: Right side	emergency exi e, rear most em erable due to cra	ergency
392.2UCR	392.2	1	Ν	N N				ee: Carrier regis ing UCR fees fo	
393.93B3	393.93(b)(3)) 1	Y	UN	T ti S	empora ne requi	ry Seating rements of andard No.	- Vehicle must Federal Motor 2071 (?571.207	conform to Vehicle
393.93A	393.93(a)	1	Ν	N N	r		right side s	vith seat belts: B eats do not have	
396.3A1	396.3(a)(1)	1	Ν	ΝΥ	a n	ccessori nissing/b	es: Benches	l maintenance of s 1-3, left side o crash. Numero l.	
393.78	393.78	1	Ν	N N				operative/defection r empty. Not due	
396.3A1	396.3(a)(1)	1	Ν	N Y	lı a	nspection ccessori	n, repair and es: Vehicle	l maintenance of is OOS until retu 's original specif	f parts & irned
392.9BA-INACTIVEI NTRA	392.9b(a)	1	Y	UN	ll c c	NTRAST ommerc ommerc	ATE CARR cial motor v ce without a	IER Operating rehicle in intras an active USDO rier's USDOT#	a tate T number
Report Prepared By: BRIAN BAXTER		Badge #: M6055	Copy Received CHRISTOPHER	<u>By:</u> VALERO TORF		age 1 of 6			_

Χ_

_____ 03773075 NY NYMC74000503

		DRIVER	VEHICLE E	EXAMINA	TION R	LEPORT Query Central 3.4
New York State De Commercial Motor 50 Wolf Road, POE Albany, NY 12232 Phone:	-	on	Report Number: NYMC74000503 Inspection Date: 01/31/2023 Start: 11:06 AMET End: 02:56 PM ET Inspection Level: I - Full HM Inspection Type: None			
BFNY LLC PO BOX 123 CATO, NY 13033-0 JSDOT#: 03773075	Phon			Li Da Ca	cense#: ate of Bi oDriver:	rth:
MC/MX#: 00000000 State#:	га Га	x#:			cense#: ate of Bi	rth: State:
Vio Code	Section	<u>Unit</u>	OOS Citation	<u>#</u> Verify	Crash	Violations Discovered inactive on 4/26/2022, due to failure to subn
392.2RG	401.1A-R	1	Ν	Ν	Ν	to safety audit. 401.1A-R Operating a passenger CMV with an incorrect registration: Bus registered in Montana, not NY as required. Carrier has no physical address in MT.
393.81	393.81	1	Ν	Ν	Y	Horn inoperative: Horn inoperative.
393.60C	393.60(c)	1	Ν	Ν	Y	Damaged or discolored windshield: Windshield smashed.
393.95A	393.95(a)	1	Ν	Ν	Ν	No/discharged/unsecured fire extinguisher: Fire extinguisher discharged prior to crash.
393.30	393.30	1	Ν	Ν	Y	Improper battery installation: Left side, auxiliar battery unsecured.
393.75A3	393.75(a)(3)	1	Y	U	Y	Tire-flat and/or audible air leak: Axle 2 left side, both tires flat and off the bead.
393.207A	393.207(a)	1	Y	U	Y	Axle positioning parts defective/missing: A 2, both sides, sway bar broken.
396.3A1-EC	396.3(a)(1)	1	Y	U	Y	Bus - Electrical Mountings broken or unsecured: Electrical mountings throughou the bus are broken. Wiring exposed throughout.
393.11	393.11	1	Y	U	Y	No or defective lighting devices or reflective material as required: Left side, rear turn signal. Lens broken.
393.91-SNS	393.91	1	Y	U	Ν	Motor Coach or other Passenger Carrying vehicle operating with seating, occupied or not, not secured in a workmanlike manner.: Rear, right side. Two bench seats added in non-workman like manner. Self tapping, lag screws securing seat to floor. Riveted to sig door. Two small tack welds.
396.3A1	396.3(a)(1)	1	Y	U	Y	Inspection, repair and maintenance of part & accessories: Left, front wheel assembly broken off as a result of the crash.
383.23A2	383.23(a)(2)	D	Y	Ν	N	Operating a CMV without a CDL: Operating CMV without a CDL on 01/28/2023
391.41A1-P	391.41(a)(1)	D	Y	Ν	Ν	Operating a passenger-carrying vehicle without possessing a valid medical certificate.: Driver does not possess a valid medical examination certificate.
390.21TA	390.21T(a)	1	Ν	Ν	Ν	CMV not marked in accordance with regulations: Carrier USDOT # not displayed or either side as required.
396.17C	396.17(c)	1	Ν	Ν	Ν	Operating a CMV without proof of a periodic
Report Prepared By: BRIAN BAXTER X		<u>Badge #:</u> M6055	Copy Receive CHRISTOPHE X		TORRES	Page 2 of 6

Commercial Motor Vehicle Inspections 50 Wolf Road, POD 5-3 Albary, NY 12032 Inspection Date: 01/31/2023 Start: 11:06 AMET End: 02:56 PM E Inspection Level: 1 - Full HM Inspection Type: None LBFNY LLC PO BOX 123 CATO, NY 13033-0123 USDOT#: 03773075 MC/MX#: 0000000 Fax#: Driver: VALEPO TORRES, CHRISTOPHER G License#: State: State: Vio Code Section Unit OOS Citation # Verify Crash Verify Crash Violations Discovered inspection: Bus has no proof any periodi/annual safety inspection. 390.33-XS 390.33 1 Y U N Operating a Motor Coch or other Passe were added (2 right rear), not according NHTSA standards, making the total seating secured or with wheel assembly as result of the crash. (front bumper, driver side door, multiple windows smashed, entry door, roof cave i re-exit 393.48A 393.9(a) 1 Y U Y Inspection, repair and maintenance of part inspection, repair and maintenance of part missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof cave i re-exit 393.9 393.9(a) 1 Y U Y Inspection Leve; Left headilgl broken of frash as result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof cave i re-exit 393.9 393.9(a) 1 Y U Y Inspection Leve; Left headilgl broken of fras as result of crash. (front bumper, driver side door, multiple			DRIVER	VEHICLE EX	AMINA	TION R	LEPORT Query Central 3.4	
PO BOX 123 CATO, NY 13033-0123 USDOT#: 03773075 MC/MX#: 00000000 License#: Fax#: License#: Date of Birth: State: Vio Code Section Unit OOS Citation # Verify Crash Violations Discovered inspection: Bus has no proof any periodic/annual safety inspection. State: 390.33-XS 390.33 1 Y U N Operating a Motor Coach or other Passe Carrying vehicle with seating, secured or unsecured, in excess of the manufacture designed seating capacity: 2 bench sea were added (2 right rear), not according NHTSA standards, making the total seat capacity 21 adults. No final modifier tag. 393.48A 393.48(a) 1 Y U Y Inspection, repair and maintenance of part accessories: Numerous frame/body parts missing or displaced as a result of crash. (front burger, driver side door, multiple windows smashed, entry door, roof caved i re-exit 393.9 393.9(a) 1 Y U Y Inoperative/defective brakes: Left, front accessories: Numerous frame/body parts missing or displaced as a result of crash. (front burger, driver side door, multiple windows smashed, entry door, roof caved i re-exit 393.9 393.9(a) 1 Y U Y Inoperable Required Lamp: Lamps: all required lighting due to no power. 393.3 393.30(a) 1 Y U Y Inoperable Required Lamp: Left headigi bro	New York State Department of Transportation Commercial Motor Vehicle Inspections 50 Wolf Road, POD 5-3 Albany, NY 12232 Phone:				Inspection Date: 01/31/2023 Start: 11:06 AM ET End: 02:56 PM ET Inspection Level: I - Full			
State#: Date of Birth: Vio Code Section Unit OOS Citation # Verify Crash Violations Discovered inspection: Bus has no prof any periodic/annual safety inspection. 390.33-XS 390.33 1 Y U N Operating a Motor Coach or other Passe Carrying vehicle with seating, secured or unsecured, in excess of the manufactur designed seating capacity: 2 bench sea were added (2 right rear), not according NHTSA standards, making the total seat capacity 21 adults. No final modifier tag. 393.48A 393.48(a) 1 Y U Y Inoperative/defective brakes: Left, front brake broken off with wheel assembly at result of the crash. 396.3A1 396.3(a)(1) 1 N N Y Inspection, repair and maintenance of part accessories: Numerous frame/body parts missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof caved i re-exit 393.9 393.9(a) 1 Y U Y Inoperable Required Lamp: Lamps: all required lighting due to no power. 393.207D 393.207(d) 1 Y U Y Inoperable Required camp. Lamps: all required lighting broken off at A arm, le side. 396.3A1 396.3(a)(1) 1 N N Y Inoperable Required Lamp: Lamps: all required lightin	PO BOX 123 CATO, NY 13033		ŧ: 1997		Lie Da	cense#: ate of Bi	State: O	
390.33-XS390.331YUNOperating a Motor Coach or other Passe Carrying vehicle with seating, secured o unsecured, in excess of the manufacture designed seating capacity: 2 bench sea were added (2 right rear), not according NHTSA standards, making the total seat capacity 21 adults. No final modifier tag.393.48A393.48(a)1YUYInoperative/defective brakes: Left, front brake broken off with wheel assembly as result of the crash.396.3A1396.3(a)(1)1NYInspection, repair and maintenance of part accessories: Numerous frame/body parts missing or displaced as a result of crash.393.9393.9(a)1YUYInoperable Required Lamp: Lamps: all required lighting due to no power.393.207D393.207(d)1YUYInoperable Required Lamp: Left headligf broken off as a result of crash.396.3A1396.3(a)(1)1YUYInoperable Required Lamp: Lamps: all required lighting due to no power.393.207D393.207(d)1YUYInoperable Required Lamp: Left headligf broken off as a result of crash.396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side coil spring broken off.393.209E393.209(e)1YUYPower steering violations: All steering		00 Fax#	:					
Carrying vehicle with seating, secured o unsecured, in excess of the manufacturr designed seating capacity.: 2 bench sea were added (2 right rear), not according NHTSA standards, making the total seat capacity 21 adults. No final modifier tag.393.48A393.48(a)1YUYInoperative/defective brakes: Left, front brake broken off with wheel assembly a result of the crash.396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Numerous frame/body parts missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof caved i re-exit393.9393.9(a)1YUYInoperable Required Lamp: Lamps: all required lighting due to no power.393.9393.9(a)1YUYInoperable Required Lamp: Left headlig broken off.393.207D393.207(d)1YUYCoil spring cracked and/or broken: Axle side coil spring broken off.396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side coil spring volations: All steering	Vio Code	Section	<u>Unit</u>	OOS Citation #	Verify	<u>Crash</u>	inspection: Bus has no proof any	
396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Numerous frame/body parts missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof caved i re-exit393.9393.9(a)1YUYInoperable Required Lamp: Lamps: all required lighting due to no power.393.9393.9(a)1YUYInoperable Required Lamp: Left headligh broken off as a result of crash.393.9393.9(a)1YUYInoperable Required Lamp: Left headligh broken off as a result of crash.393.207D393.207(d)1YUYCoil spring cracked and/or broken: Axle side coil spring broken off.396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side.393.209E393.209(e)1YUYPower steering violations: All steering	390.33-XS	390.33	1	Y	U	Ν	Operating a Motor Coach or other Passeng Carrying vehicle with seating, secured or unsecured, in excess of the manufacturer's designed seating capacity.: 2 bench seats were added (2 right rear), not according to NHTSA standards, making the total seating capacity 21 adults. No final modifier tag.	
accessories: Numerous frame/body parts missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof caved i re-exit393.9393.9(a)1YUYInoperable Required Lamp: Lamps: all required lighting due to no power.393.9393.9(a)1YUYInoperable Required Lamp: Left headligh broken off as a result of crash.393.207D393.207(d)1YUYCoil spring cracked and/or broken: Axle side coil spring broken off.396.3A1396.3(a)(1)1NYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side.393.209E393.209(e)1YUYPower steering violations: All steering	393.48A	393.48(a)	1	Y	U	Y	brake broken off with wheel assembly as a	
393.9393.9(a)1YUYInoperable Required Lamp: Left headligh broken off as a result of crash.393.207D393.207(d)1YUYCoil spring cracked and/or broken: Axle side coil spring broken off.396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side.393.209E393.209(e)1YUYPower steering violations: All steering	396.3A1	396.3(a)(1)	1	Ν	Ν	Y	missing or displaced as a result of crash. (front bumper, driver side door, multiple windows smashed, entry door, roof caved in,	
393.207D 393.207(d) 1 Y U Y Coil spring cracked and/or broken: Axle side coil spring broken off. 396.3A1 396.3(a)(1) 1 N N Y Inspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side. 393.209E 393.209(e) 1 Y U Y Power steering violations: All steering	393.9	393.9(a)	1	Y	U	Y		
396.3A1 396.3(a)(1) 1 N N Y Inspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side. 393.209E 393.209(e) 1 Y U Y Power steering violations: All steering	393.9	393.9(a)	1	Y	U	Y	Inoperable Required Lamp: Left headlight broken off as a result of crash.	
396.3A1396.3(a)(1)1NNYInspection, repair and maintenance of part accessories: Axle 1, broken off at A arm, le side.393.209E393.209(e)1YUYPower steering violations: All steering	393.207D	393.207(d)	1	Y	U	Y	Coil spring cracked and/or broken: Axle 1, side coil spring broken off.	
	396.3A1	396.3(a)(1)	1	Ν	Ν	Y	Inspection, repair and maintenance of parts & accessories: Axle 1, broken off at A arm, left	
	393.209E	393.209(e)	1	Y	U	Y		
HazMat:No HM Transported.Placard:NoCargo Tank:	HazMat: No HM	Transported.					Placard: No Cargo Tank:	

State Information:

Seating Capacity With Driver: 21; Through CDLIS Yes/No: NO; Through NYSPIN/NLETS Yes/No: NO; Reason license was not checked: VENEZUELAN DL; MEC Verified Yes/No: NO;

Report Prepared By: BRIAN BAXTER

Badge #:	
M6055	

Copy Received By: CHRISTOPHER VALERO TORRES



NYMC74000503

Х

Х

	DRIVER/VEHI	CLE EXAMINATION REPORT	Query Central 3.4
New York State Departme Commercial Motor Vehic 50 Wolf Road, POD 5-3 Albany, NY 12232 Phone:	-	Report Number: Inspection Date: Start: 11:06 AM E Inspection Leve HM Inspection T	ET End:02:56 PM ET I: I - Full
LBFNY LLC PO BOX 123 CATO, NY 13033-0123 USDOT#: 03773075	Phone#:	Driver: VALERO TORRES, C License#: Date of Birth: CoDriver:	CHRISTOPHER G State: OT
MC/MX#: 00000000 State#:	Fax#:	License#: Date of Birth:	State:
		y and declare CHRISTOPHER VALERO TORRES Out of Service. le until: Valid CDL and Medical Certificate	
	ticker or operate such vehicle(s) until the	report are declared OUT OF SERVICE pursuant to the NYS Trans e OUT OF SERVICE condition(s) has been repaired. Note: OOS \	
	t to the motor carrier whose name appea listed in the violation section above, plea	ars at the top. ase sign the report when repairs are completed.	
Signature Of Repairer X:		Facility:	Date:
3) MOTOR CARRIER: Sign and return	n within 15 days of issuance, this report (ONLY if violations are entered in the violation section.	
MAILING ADDRESS: New York Stat Commercial M 50 Wolf Road Albany, New Y	otor Vehicle Inspections POD 53		
EMAIL ADDRESS:			
DO NOT SEND TICKE	TS TO THIS ADDRESS		
4) TRAFFIC TICKETS: If issued, MUS	T be returned to the COURT whose add	dress appears on the front of the TICKET.	
5) If you have any reason to question	the results of this inspection go to https:/	//dataqs.fmcsa.dot.gov.	
6) If the vehicle has NOT been repaire	ed and HAS been permanently removed	from service, initial hereand sign number 7.	
	N: I hereby certify that all violations ente compliance with the NYS Transportation	ered on this report have been corrected or have not been corrected Law and Regulations.	I in accordance with paragraph 6,

Signature	Of	Motor	Corrior	v٠
Signature	UI.	IVIOLOI	Camer	Λ.

_____ Title:____

____ Date:

Report Prepared By: BRIAN BAXTER

Badge #:	
M6055	

<u>Copy Received By:</u> CHRISTOPHER VALERO TORRES



DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

End: 02:56 PM ET

New York State Department of Transportation Commercial Motor Vehicle Inspections 50 Wolf Road, POD 5-3 Albany, NY 12232 Phone:

LBFNY LLC
PO BOX 123
CATO, NY 13033-0123
USDOT#: 03773075
MC/MX#: 00000000
State#:

Phone#:	
Fax#:	

Driver: VALERO TORRES, CHRISTOPHER	G
License#:	State: OT
Date of Birth:	
CoDriver:	
License#:	State:
Date of Birth:	

Report Number: NYMC74000503

Inspection Date: 01/31/2023

Inspection Level: 1 - Full

HM Inspection Type: None

Start: 11:06 AM ET

Inspection Notes

This carrier was shown as being under an OOS order for New Entrant Revoked - Refusal of Audit/No Contact on 4/26/2022 by a real-time query at 1/31/2023 12:14:40 PM.

Post crash inspection. Conducted at NYSDOT residency, RayBrook, NY, with NYSP Troop B CVEU, NYSDOT Justin Zimmerman, NTSB Jason Zietler and NYSP crash reconstruction team.

Crash occured on 1/28/2023 on state highway 37, Louisville, NY. 6 fatalities of bus passengers. Bus transporting workers from a local hotel to a local solar farm project. Only other vehicle involved in the crash is a box truck operated by Aero Global Logistics, USDOT 2447319. The box truck was being operated by Harly Diaz Baez, NY drivers license

Both drivers deposed by NTSB and NYSP.

Bus was previously in NYSDOT semi-annual inspection bus program. Its last inspection was in July 2021. At which time it was inspected as a 15 passenger bus. 3 seats appear to have been added since July 2021. Left rear appears to be reinstalled according to manufacturer specs. Two right rear bench seats do not match the other seats. They are simply screwed to the floor and tack welded to the wheelchair door. These two bench seats do not have seat belts.

Unable to perform a full inspection of the bus brake system due to lack of power to the vehicle. Front left brake demolished. Front right wheel pulled and rotor and pad thickness examined with no violations. Brake fluid within normal range in reservoir. Unable to inspect emergency / parking brake, but cable is intact.

Bus driver posesses Venezuela credentials, which are not valid for CMV operations. FMCSA and NTSB conducting further investigation on the driver.

FMCSA, NTSB and NYSDOT Silverstein conducting investigation at carriers PPOB in conjuction with this inspection.

Inspection of box truck to be performed by NYSP CVEU.

Special Studies No Special Study Data Recorded

Report Prepared By: BRIAN BAXTER

Badge #:	
M6055	

Х

<u>Copy Received By:</u> CHRISTOPHER VALERO TORRES



NYMC74000503

Х

DRIVER/VEHICLE EXAMINATION REPORT

New York State Department of Transportation Commercial Motor Vehicle Inspections 50 Wolf Road, POD 5-3 Albany, NY 12232 Phone:

LBFNY LLC PO BOX 123 CATO, NY 13033-0123 USDOT#: 03773075 MC/MX#: 0000000 State#:

Phone#:	
Fax#:	

Report Number: NYMC74000503 Inspection Date: 01/31/2023 Start: 11:06 AMET End: 02:56 PM ET Inspection Level: I - Full HM Inspection Type: None

Query Central 3.4

Driver: VALERO TORRES, CHRISTOPHER	G
License#:	State: OT
Date of Birth:	
CoDriver:	
License#:	State:
Date of Birth:	

Report Prepared By: BRIAN BAXTER Badge #: M6055

Х

Copy Received By:CHRISTOPHER VALERO TORRES



Χ_