



Motor Carrier Attachment 49:

Vehicle 6 NJSP Driver/Vehicle Inspection Report

Cranbury, N.J; 06/07/2014

HWY14MH012

(2 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 2.14.1.1



NEW JERSEY STATE POLICE
 [REDACTED]
TRANSPORTATION SAFETY BUREAU
PRINCETON, NJ 08540
 Phone: [REDACTED] Fax: ([REDACTED])

Report Number: [REDACTED]
 Inspection Date: 06/12/2014
 Start: 9:08:00 AM ET End: 1:28:01 PM ET
 Inspection Level: I - Full
 HM Inspection Type: None

4 WAY TRANSPORT LLC

PHILADELPHIA, PA 19120

USDOT#: 02402309

MC/MX#: 826327

State#:

Location: GEORGES TOWING

Highway: NJTPK

County: MIDDLESEX, NJ

Phone#: [REDACTED]
 Fax#: [REDACTED]

Driver: [REDACTED] State: PA
 License#: [REDACTED]
 Date of Birth: [REDACTED]
 CoDriver:
 License#: [REDACTED] State:
 Date of Birth: [REDACTED]

MilePost: 0 Shipper: [REDACTED]
 Origin: VINELAND, NJ Bill of Lading: MULTIPLE
 Destination: ASSONET, MA Cargo: REFRIGERATED FOODS

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2006	PA	[REDACTED]	786	1FUJBBCK46[REDACTED]	52,000			
2	ST	TRIM	1998	PA	[REDACTED]	427	1PT01ANH3V[REDACTED]	65,000			

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	1 1/4	1 3/4	2	1 3/4	1 1/2
Left	1 1/8	2 1/4	2 1/8	1 3/4	1 3/8
Chamber	L-20	L-30	L-30	C-30	C-30

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.9AA1	392.9a(a)(1)	1	Y	SP5424288	U	N	Operating without the Required Operating Authority
393.45DLUV	393.45(d)	1	Y	SP5424289	U	N	Brake Connections with Leaks Under Vehicle, other than proper connection. Right side, 2nd axle, service side brake hose audible air leak behind hose fitting.
393.45B2	393.45(b)(2)	1	Y		U	N	Brake hose or tubing chafing/worn through outer reinforcement ply. 3rd axle, right side service side.
396.5B	396.5(b)	1	N		N	N	Engine Oil leak, rear main seal. excessive oil on rear of engine & oil pan.
396.5B	396.5(b)	1	N		N	N	Transmission Oil leak, rear seal of transmission output shaft
390.21A	390.21(a)	1	N		N	N	Not marked in accordance with regulations, Letters US not placed before DOT# on both sides of vehicle.
393.9	393.9(a)	2	N		N	N	Inoperable required lamps - Right front Clearance lamp missing. Left front & right rear clearance lamps inop on cargo box.
393.75A	393.75(a)	2	Y		U	N	Flat tire, Left side, 5th axle, inner tire
392.2	392.2	2	N		N	N	State License Plate violation, Unclear rear license plate. Characters covered by grease. (39:3-33)
395.8E	395.8(e)	D	Y		N	N	False Log. Redundant & Destroyed log book pages for 6/4, 6/5 & 6/6/14 were found inside sleeper birth. Hours differ from initial log pages presented

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks: Post Crash

Report Prepared By:

Badge #:

Copy Received By:

Page 1 of 2

X [REDACTED] X [REDACTED]

X



02402309 NJ NJSPDP002368