
NATIONAL TRANSPORTATION SAFETY BOARD Investigative Hearing Alaska Airlines Flight 1282 Boeing 737-9, N704AL

Left Mid Exit Door Plug Separation in Portland, OR January 5, 2024



Operational Factors Group Chairman's Factual Report -Attachment 8 - CBT Training Modules [Excerpts] (10 Pages)

NTSB Investigation No. DCA24MA063

DCA24MA063

OPERATIONAL FACTORS

Attachment 8 CBT Training Modules [Excerpts] April 18, 2024 The following slides were provided by Alaska Airlines:

737-9 MAX Initial Familiarization CBT slide (at time of accident)



Figure 1. Relevant CBT slide prior to the accident.

New 737-9 MAX System Airplane General CBT slides (postaccident)

The following slides will be included in initial ground school and captain upgrade training:




Figure 2. New 737-9 CBT slide




Figure 3. New 737-9 CBT slide.




Figure 4. New 737-9 CBT slide.



Figure 5. New 737-9 CBT slide.



Figure 6. New 737-9 CBT slide.

New CQ Quarter 2 CBT slides 2024 (postaccident)



Figure 7. New CQ Quarter 2 CBT slide.



Figure 8. New CQ Quarter 2 CBT slide.




Figure 9. New CQ Quarter 2 CBT slide.

Updated Instructors Guide



Q74 Hands On Emergency Equipment Instructor Guide September 2019

REVISION SUMMARY

Date	Affected Page(s)	Summary of Change
April 2019	All	Mock 1 renovation; reorganize for clarity
Sep 2019	All	New Maintenance Contractor New Equipment Cabinet Corrected <u>Sharepoint</u> URL for TREQ
04-12-2024	18	 Added verbiage on restoring boom mic in the MAX







- 8. Ensure Regulator Control Knob set to 100% and centered between stowage box doors.
- 9. Discuss with students about restoring Boom Mic communication in the MAX.
 - Stow the Oxygen mask
 - Close the stowage doors (specifically connected to the right stowage door)
 - Press the TEST/RESET switch
 - Ensure the OXY ON flag is not showing

Figure 10. Updated Instructors Guide.