



Michael Folkerts
Air Safety Investigator
Central Division

Date: May 19, 2022
Subject: CEN22FA203, Passenger Interview
Contact: Billy McClements

Mr. McClements stated that the pilot flew the accident airplane to Clifton Municipal Airport (7F7), Clifton, Texas. Mr. McClements boarded the airplane and flew with the pilot from 7F7 to Roger M. Dreyer Memorial Airport (T20), Gonzales, Texas, where equipment for an oil services company was dropped off. The airplane was refueled at T20 and flown back to 7F7, where Mr. McClements disembarked. The pilot departed solo from 7F7 to return to his home airport.

Mr. McClements stated that engine oil was added at T20, based on a high engine oil temperature. He did not observe any other issues with the aircraft. He also did not observe any unusual or erratic behavior by the pilot and reported that the pilot was in good spirits.