



NTSB ERA22LA310

Cub Crafters CC11-160 (N55JV)

Investigative Photographs



Photo 1: Overview of the airplane after it was recovered from the accident site (Photo Courtesy of FAA)



Photo 2: Overview of the farm field that was used for takeoff (Photo Courtesy of FAA)



Photo 3: View of the substantial damage sustained to the left wing lift strut (Photo Courtesy of FAA)



Photo 4: View of the substantial damage sustained to the vertical stabilizer and rudder (Photo Courtesy of FAA)



Photo 5: View of the forward seat control stick and rocker trim switch (Photo Courtesy of FAA)



Photo 6: View of the nose UP/DOWN horizontal trim positioned to full nose down (Photo Courtesy of FAA)



Photo 7: View of the nose UP/DOWN horizontal trim positioned to neutral (Photo Courtesy of FAA)