

NTSB ERA23FA001

N262TA, Cessna 172

Hermantown, Minnesota

Photo Array




Photo 1: Front view of home where airplane impacted. Note outline of damage to second floor roof.



Photo 2: View of backside of damaged home where the airplane exited.



Photo 3: View of main wreckage site detailing latitude, longitude, magnetic heading and elevation.



Photo 4: View of horizontal and vertical stabilizer up against garage with their respective control surfaces still in place.



Photo 5: View of main wreckage site looking towards damaged home.



Photo 6: View of main wreckage site taken from second story floor of house.



Photo 7: View of propeller assembly showing both blades and crushed spinner. Note the s-bending and chordwise scraping.



Photo 8: View of engine after removal from debris pile.



Photo 9: View of cockpit instrument panel at accident site.(Courtesy of Textron)



Photo 10: View of left side of engine at wreckage site.




Photo 10: View of engine after removal of valve covers at exam location. (Courtesy of Lycoming)



Photos 11, 12, 13: View of attitude indicator, turn coordinator and vacuum system after removal.