


ERA24LA039

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Bent Frame Tube (Courtesy of FAA)



Photograph 3 - Separated Frame Tube (Courtesy of FAA)



Photograph 4 - Second Separated Frame Tube (Courtesy of FAA)



Photograph 5 - Third Separated Frame Tube (Courtesy of FAA)



Photograph 6 - Elevator Trim Control (Courtesy of FAA)