



**Photo 1 – Substantial Damage to Tailboom**



**Photo 2 – Damage to Tailrotor Driveshaft and Vertical Fins**



**Photo 3 – Closeup of Damage to Tailrotor Driveshaft**