

ERA23FA006

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the fuselage and left wing at the accident site.



Photograph 2 - View of the cockpit at the accident site.



Photograph 3 - View of angular cut wood found near the main wreckage.



Photograph 4 - View of angular cut wood at the accident site.



Photograph 5 - View of the top of the engine after recovery from the accident site.



Photograph 6 - View of the rear of the engine after recovery from the accident site.