



**Photo 1 – View of main wreckage of N319RL showing structural damage of entire aircraft.**





**Photo 2 – View of N319RL after wreckage recovery, showing structural damage.**





**Photo 3 – View of empennage showing black tire skid mark.**





**Photo 4 – View of yellow paint transfer mark on top of fuselage behind canopy.**





**Photo 5 – View of N203DD in field showing structural damage throughout aircraft.**





**Photo 6 – View of semicircular damage on leading edge of left inboard wing.**





**Photo 7 – View of red paint transfer on leading edge of right wing.**