



**Photo 1 – View of airplane from the left side showing right wing damage**



**Photo 2 – View of airplane from the front showing forward crush damage**