



Photo 1 – View of motor mount showing a bend in the lower section.



Photo 2 – View of damaged firewall