



Photo 1 – Damage to Left Tail Boom Assembly



Photo 2 – Damage to Right Tail Boom Assembly



Photo 3 – VEMD Post-Accident



Photo 4 – Helicopter’s Right Side, Next to Hangar, After Accident