



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA044



Photo 1 – View of Propeller with Feathers (Photo Courtesy of FAA)



Photo 2 – View of Broken Windscreen (Photo Courtesy of FAA)



Photo 3 – View of Additional Bird Impact Damage on Right Wing (Photo Courtesy of FAA)