

Photo 1 – Crack to composite fuselage structure (photo provided by FAA)



Photo 2 – Right wing and leading edge damage (photo provided by FAA)