



Photo 1 – Picture of Airplane at Accident Site (FAA)



Photo 2 - Loose Aux Fuel Tank Fitting in RH Wing (FAA)



Photo 3 – Fuel Stain at Root of RH Wing (FAA)