



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA23LA118**



**Photo 1 – View of airplane from right wing with engine on fire (Photo courtesy of Mark Chemacki)**



**Photo 2 – View of airplane after fire extinguished (Photo courtesy of RDU Airport Operations)**



**Photo 3 – Close-up view of damage after fire extinguished (Photo courtesy of RDU Airport Operations)**



**Photo 4 – View of fire damaged engine mounts and firewall (Photo courtesy of FAA)**