



Photo 1 – Aerial image of accident site



Photo 2 – Main wreckage



Photo 3 – Main wreckage



Photo 4 – Main wreckage



Photo 5 – Main wreckage



Photo 6 – Empennage (Source: Twin Commander LLC)