

ERA23FA194

INVESTIGATION PHOTOGRAPHS



Photograph - Turbocharger Switch in Cockpit (Courtesy of Owner)



Photograph 2 - Accident Site



Photograph 3 - Left Wing



Photograph 4 - Left Rudder



Photograph 5 - Engine And Propeller



Photograph 6 - Turbocharger Wastegate