


CEN23LA062


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantially Damaged Airplane (Courtesy of FAA)




Photograph 2 - Burned Airplane Instrument Panel (Courtesy of FAA)



Photograph 3 - Missing Teeth on Camshaft Gear



Photograph 4 - Camshaft Teeth Found in Oil Sump



Part Number
655516

Photograph 5 - Camshaft Gear Highlighting the Part Number