

CEN24LA127

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right main landing gear separated (Courtesy of Pilot)



Photograph 2 - Deformation noted to the right aileron (Courtesy of Pilot)

INVESTIGATION PHOTOGRAPHS



Photograph 3 - Deformation noted to the fuselage (Courtesy of Pilot)

INVESTIGATION PHOTOGRAPHS