

ERA24LA146

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Main Wreckage (Courtesy of FAA)**



**Photograph 2 - Debris Path of Left Flap And Left Main Landing Gear (Courtesy of FAA)**





**Photograph 3 - Right Elevator Damage (Courtesy of FAA)**