




**Photo 1 – Main Wreckage**



**Photo 2 – Left Wing Damage**





**Photo 3 - Propeller**



**Photo 4 – Propeller Removed**





**Photo 5 – Propeller at Teardown Examination (Photo Courtesy of Textron)**



**Photo 6 – Propeller Links (Photo Courtesy of Textron)**