

ERA23FA024

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage view looking forward with heading and location tags.



Photograph 2 - View of right wing damage.



Photograph 3 - View of right propeller and engine looking aft.



Photograph 4 - View of cockpit and cabin damage looking aft.



Photograph 5 - View of left propeller and engine looking aft. Note: Resting on top of damaged vehicle.



Photograph 6 - View of left wing damage.



Photograph 7 - View of left side of empennage, elevator, and rudder.



Photograph 8 - View of right side of empennage, elevator, and rudder.