



Photo 1: Photo of Right Horizontal Stabilizer and Right Elevator Damage



Photo 2: View of Right Engine Inboard Lower Cowl with Three Missing Fasteners



Photo 3: View of the Left Engine Inboard Lower Cowl